



## Distributor with three quick connectors, external thread, brass

Pressure:

from 0 to 35 bar the maximum static pressure

The temperature of the medium and the environment:

from -20 ° C to + 100 ° C

Building:

Brass

The spring latch ring, balls:

stainless steel

Sealing:

NBR

Name	Złącze	Trójnik	Szybkozłączka
245.51	G1/4 zewnętrzny	256.01	243.02
245.52	G3/8 zewnętrzny	256.01	243.02
245.53	G1/2 zewnętrzny	256.02	243.03