



## Vacuum gauge and manowakuometr contacts, connection bottom

Execution:

contact manometer Bourd  
contacts (contact type 821

Application:

contact manometers gas li  
niekryształizujących of the m  
alloys

Accuracy:

1.0

Housing:

Stainless steel 1.4301

Glass:

Thin glass

Connection:

Brass (<100 bar)

Stainless steel 1.4301 (> 1

The temperature of the medium:

max 80 ° C

Ambient temperature:

from -20°C to + 70°C

| Name   | Zakres ciśnień | Średnica w mm | Screw |
|--------|----------------|---------------|-------|
| 3300/1 | -1 / +1,5 bar  | 160           | G1/2  |