



## Mbar pressure gauge, connection bottom

Execution:

manometer canned

Application:

gases, dry and non-aggress

Accuracy:

1.6

Housing:

Black steel for diameters of

Stainless steel for diamete

Glass:

Acrylic for diameters of 63

The smooth glass for diameters of 100 mm

Brass

up to 100 ° C

max 80 ° C for diameters of 100 mm with rear connection

from -20°C to + 60°C

Connection:

The temperature of the medium:

Ambient temperature:

Name	Zakres ciśnień	Średnica w mm	Screw
5812	0 - 40 mbar	63	G1/4
5813	0 - 60 mbar	63	G1/4
5814	0 - 100 mbar	63	G1/4
5815	0 - 160 mbar	63	G1/4
5816	0 - 250 mbar	63	G1/4
5817	0 - 400 mbar	63	G1/4
6811	0 - 25 mbar	100	G1/2
6812	0 - 40 mbar	100	G1/2
6813	0 - 60 mbar	100	G1/2
6814	0 - 100 mbar	100	G1/2
6815	0 - 160 mbar	100	G1/2
6816	0 - 250 mbar	100	G1/2
6817	0 - 400 mbar	100	G1/2