



Gun to blow air nozzle dissipating, aluminum

| | |
|-----------------------|--------------------|
| Pressure: | 10bar |
| Pressure recommended: | 2 to 6 bar |
| Working temperature: | -10 ° C to +50 ° C |
| Connection nozzle: | M12x1,25 |

| Name | Złącze |
|--------|--------|
| 22 A/D | LW 6 |
| 22 B/D | LW 9 |
| 22 C/D | LW 13 |
| 22 K/D | DN 7,2 |