



## Straight GE

| Name        | D | G1       | SW1 | SW2 |
|-------------|---|----------|-----|-----|
| GE4LLM6x1   | 4 | M6x1K    | 11  | 10  |
| GE4LLM8x1   | 4 | M8x1K    | 11  | 10  |
| GE4LLM10x1  | 4 | M10x1K   | 11  | 10  |
| GE4LLR1/8   | 4 | R1/8K    | 11  | 10  |
| GE6LLM6x1   | 6 | M6x1K    | 11  | 12  |
| GE6LLM8x1   | 6 | M8x1K    | 11  | 12  |
| GE6LLM10x1  | 6 | M10x1K   | 11  | 12  |
| GE6LLR1/8   | 6 | R1/8K    | 11  | 12  |
| GE6LR1/4    | 6 | R1/4K    | 12  | 14  |
| GE8LLM6x1   | 8 | M6x1K    | 14  | 14  |
| GE8LLM8x1   | 8 | M8x1K    | 14  | 14  |
| GE8LLM10x1  | 8 | M10x1K   | 14  | 14  |
| GE8LLR1/8   | 8 | R1/8K    | 14  | 14  |
| GE8LM12x1.5 | 8 | M12x1.5K | 17  | 17  |
| GE8LR1/4    | 8 | R1/4G    | 17  | 17  |
| GE8LM14x1.5 | 8 | M14x1.5G | 19  | 19  |