



Grease straight to the head conical

Name	Screw
K6x1	M6x1
K8x1	M8x1
K8x1,25	M8x1.25
K1/8	R1/8
K10x1	M 10x1
K10x1,25	M10x1.25
K10x1,5	M10x1.5
K12x1	M 12x1
K12x1,5	M 12x1,5
K12x1,75	M12x1.75
K1/4	R1/4
K14x1	M 14x1
K14x1,25	M14x1.25
K14x1,5	M 14x1,5
K14x1,75	M14x1.75
K16x1,5	M 16x1,5
K3/8	G3/8