

GMM 100 Pressure gauge connection bottom



Glycerine pressure gauges (Ø 100) with radial connection, a pressure of up to -1 MPa – 100 MPa. Particularly robust, used for pumps, compressors, power supplies, hydraulic systems, high uzdatniaczach water cooling systems

Name	Gwint BSP	Średnica	Zakres ciśnień
GMM100 -1/0	1/2"	100	-1 / 0,0 bar
GMM100-1	1/2"	100	0 - 1,0 bar
GMM100-1,6	1/2"	100	0 - 1,6 bar
GMM100-1/3	1/2"	100	-1 / +3,0 bar
GMM100-2,5	1/2"	100	0 - 2,5 bar
GMM100-4	1/2"	100	0 - 4,0 bar
GMM100-6	1/2"	100	0 - 6,0 bar
GMM100-10	1/2"	100	0 - 10,0 bar
GMM100-16	1/2"	100	0 - 16,0 bar
GMM100-25	1/2"	100	0 - 25,0 bar
GMM100-40	1/2"	100	0 - 40,0 bar
GMM100-60	1/2"	100	0 - 60,0 bar
GMM100-160	1/2"	100	0 - 160,0 bar
GMM100-250	1/2"	100	0 - 250,0 bar
GMM100-400	1/2"	100	0 - 400,0 bar
GMM100-600	1/2"	100	0 - 600,0 bar
GMM100-1000	1/2"	100	0 - 1000,0 bar