

## Static seals O-RING-metric



**Material:** rubber (NBR 70)

**Operating temperature:** -30 °C + 110 °C

**Resistance to media:**

- Mineral oils and greases
- Oils of vegetable or animal origin
- Non-flammable hydraulic fluids type the HSA, HSB
- Water to +100 °C
- Diluted solutions of acids and bases to 50 °C

Name	d (rys.)	T
OR2,75x1,6-70	2,75	1,60
OR3,10x1,6-70	3,10	1,60
OR4,1x1,6-70	4,10	1,60
OR5,1x1,6-70	5,10	1,60
OR6,1-1,6-70	6,10	1,60
OR7,1x1,6-70	7,10	1,60
OR8,1x1,6-70	8,10	1,60
OR9,1x1,6-70	9,10	1,60
OR10,1x1,6-70	10,10	1,60
OR11,1x1,6-70	11,10	1,60
OR12,1x1,6-70	12,10	1,60
OR13,1x1,6-70	13,10	1,60
OR14,1x1,6-70	14,10	1,60
OR15,1x1,6-70	15,10	1,60
OR16,1x1,6-70	16,10	1,60
OR17,1x1,6-70	17,10	1,60
OR18,1x1,6-70	18,10	1,60
OR19,1x1,6-70	19,10	1,60
OR22,1x1,6-70	22,10	1,60
OR25,1x1,6-70	25,10	1,60
OR27,1x1,6-70	27,10	1,60
OR29,1x1,6-70	29,10	1,60
OR32,1x1,6-70	32,10	1,60
OR35,1x1,6-70	35,10	1,60
OR37,1x1,6-70	37,10	1,60
OR2x2-70	2	2
OR2,5x2-70	2,50	2
OR3x2-70	3	2

<b>Name</b>	<b>d (rys.)</b>	<b>T</b>
OR3,5x2-70	3,50	2
OR4x2-70	4	2
OR4,5x2-70	4,50	2
OR5x2-70	5	2
OR5,5x2-70	5,50	2
OR6x2-70	6	2
OR6,5x2-70	6,50	2
OR7,5x2-70	7,50	2
OR7x2-70	7	2
OR8x2-70	8	2
OR8,5x2-70	8,50	2
OR9x2-70	9	2
OR9,5x2-70	9,50	2
OR10x2-70	10	2
OR10,5x2-70	10,50	2
OR11x2-70	11	2
OR11,5x2-70	11,50	2
OR12x2-70	12	2
OR12,5x2-70	12,50	2
OR13x2-70	13	2
OR13,5x2-70	13,50	2
OR14x2-70	14	2
OR14,5x2-70	14,50	2
OR15x2-70	15	2
OR15,5x2-70	15,50	2
OR16x2-70	16	2
OR16,5x2-70	16,50	2
OR17x2-70	17	2
OR17,5x2-70	17,50	2
OR18x2-70	18	2
OR18,5x2-70	18,50	2
OR19x2-70	19	2
OR19,5x2-70	19,50	2
OR20x2-70	20	2
OR20,5x2-70	20,50	2
OR21x2-70	21	2
OR21,5x2-70	21,50	2
OR22x2-70	22	2
OR22,5x2-70	22,50	2
OR23x2-70	23	2
OR23,5x2-70	23,50	2
OR24x2-70	24	2
OR24,5x2-70	24,50	2
OR24x2-70	24	2
OR24,5x2-70	24,50	2
OR25x2-70	25	2
OR25,5x2-70	25,50	2

Name	d (rys.)	T
OR26x2-70	26	2
OR26,5x2-70	26,50	2
OR27x2-70	27	2
OR27,5x2-70	27,50	2
OR28x2-70	28	2
OR28,5x2-70	28,50	2
OR29x2-70	29	2
OR29,5x2-70	29,50	2
OR30x2-70	30	2
OR30,5x2-70	30,50	2
OR31x2-70	31	2
OR31,5x2-70	31,50	2
OR32x2-70	32	2
OR32,5x2-70	32,50	2
OR33x2-70	33	2
OR33,5x2-70	33,50	2
OR34x2-70	34	2
OR34,5x2-70	34,50	2
OR35x2-70	35	2
OR35,5x2-70	35,50	2
OR36x2-70	36	2
OR36,5x2-70	36,50	2
OR37x2-70	37	2
OR37,5x2-70	37,50	2
OR38x2-70	38	2
OR38,5x2-70	38,50	2
OR39x2-70	39	2
OR39,5x2-70	39,50	2
OR40x2-70	40	2
OR41x2-70	41	2
OR42x2-70	42	2
OR43x2-70	43	2
OR44x2-70	44	2
OR45x2-70	45	2
OR46x2-70	46	2
OR47x2-70	47	2
OR48x2-70	48	2
OR49x2-70	49	2
OR50x2-70	50	2
OR51x2-70	51	2
OR52x2-70	52	2
OR53x2-70	53	2
OR54x2-70	54	2
OR55x2-70	55	2
OR56x2-70	56	2
OR57x2-70	57	2
OR58x2-70	58	2

<b>Name</b>	<b>d (rys.)</b>	<b>T</b>
OR59x2-70	59	2
OR60x2-70	60	2
OR61x2-70	61	2
OR62x2-70	62	2
OR63x2-70	63	2
OR64x2-70	64	2
OR65x2-70	65	2
OR66x2-70	66	2
OR67x2-70	67	2
OR68x2-70	68	2
OR69x2-70	69	2
OR70x2-70	70	2
OR71x2-70	71	2
OR72x2-70	72	2
OR72x2-70	72	2
OR73x2-70	73	2
OR74x2-70	74	2
OR75x2-70	75	2
OR76x2-70	76	2
OR77x2-70	77	2
OR78x2-70	78	2
OR79x2-70	79	2
OR80x2-70	80	2
OR81x2-70	81	2
OR82x2-70	82	2
OR83x2-70	83	2
OR84x2-70	84	2
OR85x2-70	85	2
OR86x2-70	86	2
OR87x2-70	87	2
OR88x2-70	88	2
OR89x2-70	89	2
OR90x2-70	90	2
OR91x2-70	91	2
OR92x2-70	92	2
OR93x2-70	93	2
OR94x2-70	94	2
OR95x2-70	95	2
OR96x2-70	96	2
OR97x2-70	97	2
OR98x2-70	98	2
OR99x2-70	99	2
OR100x2-70	100	2
OR3,3x2,4-70	3,30	2,40
OR3,6x2,4-70	3,60	2,40
OR4,3x2,4-70	4,30	2,40
OR4,6x2,4-70	4,60	2,40

Name	d (rys.)	T
OR5,3x2,4-70	5,30	2,40
OR5,5x2,4-70	5,50	2,40
OR5,6x2,4-70	5,60	2,40
OR6,3x2,4-70	6,30	2,40
OR6,6x2,4-70	6,60	2,40
OR7,3x2,4-70	7,30	2,40
OR7,5x2,4-70	7,50	2,40
OR7,6x2,4-70	7,60	2,40
OR8,3x2,4-70	8,30	2,40
OR8,6x2,4-70	8,60	2,40
OR9,3x2,4-70	9,30	2,40
OR9,6x2,4-70	9,60	2,40
OR10,3x2,4-70	10,30	2,40
OR10,5x2,4-70	10,50	2,40
OR10,6x2,4-70	10,60	2,40
OR11,3x2,4-70	11,30	2,40
OR11,5x2,4-70	11,50	2,40
OR11,6x2,4-70	11,60	2,40
OR12,3x2,4-70	12,30	2,40
OR12,6x2,4-70	12,60	2,40
OR13,3x2,4-70	13,30	2,40
OR13,5x2,4-70	13,50	2,40
OR13,6x2,4-70	13,60	2,40
OR14,3x2,4-70	14,30	2,40
OR14,5x2,4-70	14,50	2,40
OR14,6x2,4-70	14,60	2,40
OR15,3x2,4-70	15,30	2,40
OR15,5x2,4-70	15,50	2,40
OR15,6x2,4-70	15,60	2,40
OR16,3x2,4-70	16,30	2,40
OR16,6x2,4-70	16,60	2,40
OR17,3x2,4-70	17,30	2,40
OR17,5x2,4-70	17,50	2,40
OR17,6x2,4-70	17,60	2,40
OR18,6x2,4-70	18,60	2,40
OR19,3x2,4-70	19,30	2,40
OR19,6x2,4-70	19,60	2,40
OR20,5x2,4-70	20,50	2,40
OR21,5x2,4-70	21,50	2,40
OR21,6x2,4-70	21,60	2,40
OR22,3x2,4-70	22,30	2,40
OR23,5x2,4-70	23,50	2,40
OR24,5x2,4-70	24,50	2,40
OR24,6x2,4-70	24,60	2,40
OR25x2,4-70	25	2,40
OR27,3x2,4-70	27,30	2,40
OR27,5x2,4-70	27,50	2,40

Name	d (rys.)	T
OR27,6x2,4-70	27,60	2,40
OR29,6x2,4-70	29,60	2,40
OR30,3x2,4-70	30,30	2,40
OR31,6x2,4-70	31,60	2,40
OR34,6x2,4-70	34,60	2,40
OR37,6x2,4-70	37,60	2,40
OR39,6x2,4-70	39,60	2,40
OR41,6x2,4-70	41,60	2,40
OR44,6x2,4-70	44,60	2,40
OR47,6x2,4-70	47,60	2,40
OR49,6x2,4-70	49,60	2,40
OR51,6x2,4-70	51,60	2,40
OR54,6x2,4-70	54,60	2,40
OR57,6x2,4-70	57,60	2,40
OR59,6x2,4-70	59,60	2,40
OR61,6x2,4-70	61,60	2,40
OR64,6x2,4-70	64,60	2,40
OR67,6x2,4-70	67,60	2,40
OR69,6x2,4-70	69,60	2,40
OR4x2,5-70	4	2,50
OR4,6x2,5-70	4,60	2,50
OR5x2,5-70	5	2,50
OR5,5x2,5-70	5,50	2,50
OR6x2,5-70	6	2,50
OR6,5x2,5-70	6,50	2,50
OR7x2,5-70	7	2,50
OR7,5x2,5-70	7,50	2,50
OR8x2,5-70	8	2,50
OR8,5x2,5-70	8,50	2,50
OR9x2,5-70	9	2,50
OR9,5x2,5-70	9,50	2,50
OR10x2,5-70	10	2,50
OR10,5x2,5-70	10,50	2,50
OR11x2,5-70	11	2,50
OR11,5x2,5-70	11,50	2,50
OR12x2,5-70	12	2,50
OR12,5x2,5-70	12,50	2,50
OR13x2,5-70	13	2,50
OR13,5x2,5-70	13,50	2,50
OR14x2,5-70	14	2,50
OR14,5x2,5-70	14,50	2,50
OR15x2,5-70	15	2,50
OR15,5x2,5-70	15,50	2,50
OR16x2,5-70	16	2,50
OR16,5x2,5-70	16,50	2,50
OR17x2,5-70	17	2,50
OR17,5x2,5-70	17,50	2,50

Name	d (rys.)	T
OR18x2,5-70	18	2,50
OR18,5x2,5-70	18,50	2,50
OR19x2,5-70	19	2,50
O19,5x2,5-70	19,50	2,50
OR20x2,5-70	20	2,50
OR20,5x2,5-70	20,50	2,50
OR21x2,5-70	21	2,50
OR21,5x2,5-70	21,50	2,50
OR22x2,5-70	22	2,50
OR22,5x2,5-70	22,50	2,50
OR23x2,5-70	23	2,50
OR23,5x2,5-70	23,50	2,50
OR24x2,5-70	24	2,50
OR24,5x2,5-70	24,50	2,50
OR25x2,5-70	25	2,50
OR25,5x2,5-70	25,50	2,50
OR26x2,5-70	26	2,50
OR26,5x2,5-70	26,50	2,50
OR27x2,5-70	27	2,50
OR27,5x2,5-70	27,50	2,50
OR28x2,5-70	28	2,50
OR28,5x2,5-70	28,50	2,50
OR29x2,5-70	29	2,50
OR29,5x2,5-70	29,50	2,50
OR30x2,5-70	30	2,50
OR30,5x2,5-70	30,50	2,50
OR31x2,5-70	31	2,50
OR31,5x2,5-70	31,50	2,50
OR32x2,5-70	32	2,50
OR32,5x2,5-70	32,50	2,50
OR33x2,5-70	33	2,50
OR33,5x2,5-70	33,50	2,50
OR34x2,5-70	34	2,50
OR34,5x2,5-70	34,50	2,50
OR35x2,5-70	35	2,50
OR35,5x2,5-70	35,50	2,50
OR36x2,5-70	36	2,50
OR36,5x2,5-70	36,50	2,50
OR37x2,5-70	37	2,50
OR37,5x2,5-70	37,50	2,50
OR38x2,5-70	38	2,50
OR38,5x2,5-70	38,50	2,50
OR39x2,5-70	39	2,50
OR39,5x2,5-70	39,50	2,50
OR40x2,5-70	40	2,50
OR41x2,5-70	41	2,50
OR42x2,5-70	42	2,50

Name	d (rys.)	T
OR43x2,5-70	43	2,50
OR44x2,5-70	44	2,50
OR45x2,5-70	45	2,50
OR46x2,5-70	46	2,50
OR47x2,5-70	47	2,50
OR48x2,5-70	48	2,50
OR49x2,5-70	49	2,50
OR50x2,5-70	50	2,50
OR51x2,5-70	51	2,50
OR52x2,5-70	52	2,50
OR53x2,5-70	53	2,50
OR54x2,5-70	54	2,50
OR55x2,5-70	55	2,50
OR56x2,5-70	56	2,50
OR57x2,5-70	57	2,50
OR58x2,5-70	58	2,50
OR59x2,5-70	59	2,50
OR60x2,5-70	60	2,50
OR61x2,5-70	61	2,50
OR62x2,5-70	62	2,50
OR63x2,5-70	63	2,50
OR64x2,5-70	64	2,50
OR65x2,5-70	65	2,50
OR3x3-70	3	3
OR3,5x3-70	3,50	3
OR4x3-70	4	3
OR4,5x3-70	4,50	3
OR5x3-70	5	3
OR5,5x3-70	5,50	3
OR6x3-70	6	3
OR6,5x3-70	6,50	3
OR7x3-70	7	3
OR7,5x3-70	7,50	3
OR8x3-70	8	3
OR8,5x3-70	8,50	3
OR9x3-70	9	3
OR9,5x3-70	9,50	3
OR10x3-70	10	3
OR10,5x3-70	10,50	3
OR11x3-70	11	3
OR11,5x3-70	11,50	3
OR12x3-70	12	3
OR12,5x3-70	12,50	3
OR13x3-70	13	3
OR13,5x3-70	13,50	3
OR14x3-70	14	3
OR14,5x3-70	14,50	3



Name	d (rys.)	T
OR15x3-70	15	3
OR15,5x3-70	15,50	3
OR16x3-70	16	3
OR16,5x3-70	16,50	3
OR17,5x3-70	17,50	3
OR18x3-70	18	3
OR17x3-70	17	3
OR18,5x3-70	18,50	3
OR19x3-70	19	3
OR19,5x3-70	19,50	3
OR20x3-70	20	3
OR20,5x3-70	20,50	3
OR21x3-70	21	3
OR21,5x3-70	21,50	3
OR22x3-70	22	3
OR22,5x3-70	22,50	3
OR22,2x3-70	22,20	3
OR19,2x3-70	19,20	3
OR23x3-70	23	3
OR23,5x3-70	23,50	3
OR24x3-70	24	3
OR24,2x3-70	24,20	3
OR24,5x3-70	24,50	3
OR24,6x3-70	24,60	3
OR25x3-70	25	3
OR25,5x3-70	25,50	3
OR26x3-70	26	3
OR26,2x3-70	26,20	3
OR26,5x3-70	26,50	3
OR27x3-70	27	3
OR27,5x3-70	27,50	3
OR28x3-70	28	3
OR28,5x3-70	28,50	3
OR29x3-70	29	3
OR29,2x3-70	29,20	3
OR30x3-70	30	3
OR31x3-70	31	3
OR31,5x3-70	31,50	3
OR32x3-70	32	3
OR32,2x3-70	32,20	3
OR32,5x3-70	32,50	3
OR33x3-70	33	3
OR33,5x3-70	33,50	3
OR34x3-70	34	4
OR34,2x3-70	34,20	3
OR34,5x3-70	34,50	3
OR35x3-70	35	3

<b>Name</b>	<b>d (rys.)</b>	<b>T</b>
OR35,5x3-70	35,50	3
OR36x3-70	36	3
OR36,2x3-70	36,20	3
OR36,5x3-70	36,50	3
OR37x3-70	37	3
OR37,5x3-70	37,50	3
OR38x3-70	38	3
OR38,5x3-70	38,50	3
OR39x3-70	39	3
OR39,2x3-70	39,20	3
OR39,5x3-70	39,50	3
OR40x3-70	40	3