



## Manowakuometry plastic vacuum-meters and with a single rock, connection bottom

Execution:

Application:

Accuracy:

Housing:

Connection:

The temperature of the medium:

Ambient temperature:

Bourdon tube pressure gauge

gases, liquids of low and medium viscosity, and media that do not attack

1.6

Plastics

Brass

max 60 ° C

from -20 ° C to + 60°

Name	Zakres ciśnień	Średnica w mm	Screw
110.30-K	-1 / 0,0 bar	40	G1/8
100-K	-1 / 0,0 bar	50	G1/4
6300-K	-1200 / 0,0 mbar	63	G1/4
6301-K	-1 / 0,0 bar	63	G1/4
6302-K	-1 / +0,6 bar	63	G1/4
6303-K	-1 / +1,5 bar	63	G1/4
6304-K	-1 / +3,0 bar	63	G1/4
6305-K	-1 / +5,0 bar	63	G1/4
6306-K	-1 / +9,0 bar	63	G1/4
6307-K	-1 / +15,0 bar	63	G1/4