



Vacuum gauge and manowakuometr contacts, connection bottom

Execution:

contact manometer Bourd
contacts (contact type 821

Application:

contact manometers gas li
niekryształizujących of the m
alloys

Accuracy:

1.0

Housing:

Stainless steel 1.4301

Glass:

Thin glass

Connection:

Brass (<100 bar)

Stainless steel 1.4301 (> 1

The temperature of the medium:

max 80 ° C

Ambient temperature:

from -20°C to + 70°C

Name	Zakres ciśnień	Średnica w mm	Screw
3300/1	-1 / +1,5 bar	160	G1/2