



Precision vacuum gauge, connection bottom

Execution:	pressure gauge Bourdon tu
Application:	low and medium viscous a that do not attack copper a
Accuracy:	0.6
Housing:	CrNi-steel
Glass:	Smooth glass
Connection:	Brass (<100 bar) Stainless steel (> 100 bar)
The temperature of the medium:	max 80 ° C
Ambient temperature:	from -40°C to + 60°C

Name	Zakres ciśnień	Dokładność	Średnica w mm	Screw
1158	-1 / 0,0 bar	0,005	100	G1/2
1158/1	-1 / +0,6 bar	0,010	100	G1/2
1158/2	-1 / +1,5 bar	0,020	100	G1/2