



Manometer separator to work hard, connection bottom

Execution:

Application:

Accuracy:

Housing:

Glass:

The temperature of the medium:

Ambient temperature:

Diaphragm Pressure Gauge applications

for gases and liquids, pressure can also work in aggressive

1.6

Solid construction CrNi-steel

Stainless steel - for chemical

Smooth glass - to work hard

Multilayer safety glass - for

up to 100 ° C

from -20°C to + 60°C

Name	Zakres ciśnień	Średnica w mm	Screw
PL 1911	0 - 1,0 bar	100	G1/2
PL 1912	0 - 1,6 bar	100	G1/2
PL 1913	0 - 2,5 bar	100	G1/2
PL 1914	0 - 4,0 bar	100	G1/2
PL 1915	0 - 6,0 bar	100	G1/2
PL 1916	0 - 10,0 bar	100	G1/2
PL 1917	0 - 16,0 bar	100	G1/2
PL 1918	0 - 25,0 bar	100	G1/2