



Mbar vacuum gauge, connection bottom

Execution:	manometer canned
Application:	gases, dry and non-aggress
Accuracy:	1.6
Housing:	Black steel for diameters of Stainless steel for diamete
Glass:	Acrylic for diameters of 63

Connection:

The temperature of the medium:

Ambient temperature:

The smooth glass for diameters of 100 mm

Brass

up to 100 ° C

max 80 ° C for diameters of 100 mm with rear connection

from -20°C to + 60°C

Name	Zakres ciśnień	Średnica w mm	Screw
5801	-160 / 0 mbar	63	G1/4
5802	-100 / 0 mbar	63	G1/4
5803	-60 / 0 mbar	63	G1/4
6801	-160 / 0 mbar	100	G1/2
6802	-100 / 0 mbar	100	G1/2
6803	-60 / 0 mbar	100	G1/2
6804	-25 / +15 mbar	100	G1/2
6805	-40 / +20 mbar	100	G1/2