



## Reduction of thread cylindrical, nickel-plated brass

Name	Gwint zew.	Gwint wew.	B	L	CH1
2090 1/4-1/8	1/4	1/8	8	13	17
2090 3/8-1/8	3/8	1/8	9	14	19
2090 3/8-1/4	3/8	1/4	9	14	19
2090 1/2-1/8	1/2	1/8	10	15,5	24
2090 1/2-1/4	1/2	1/4	10	15,5	24
2090 1/2-3/8	1/2	3/8	10	15,5	24
2090 3/4-3/8	3/4	3/8	12	17,5	30
2090 3/4-1/2	3/4	1/2	12	17,5	30
2090 1/8-M5	1/8	M5	6	10,5	14