



## Sectional DPA-type progressive distributor wielosekcyjny

expense / right and left output sections

Number of outputs  
operating pressure  
material execution  
supply connection  
Output connections  
mounting screws  
lubricant

0.05, 0.1, 0.15

6 ÷ 24

15 ÷ 300 bar

galvanized steel

M10x1

M10x1

M6x50

oil of 15 cSt and

### Name

SROZDZ1DPA