



GAB - Connectors

Connection 1
Sealing form 1
Connection 2
Sealing form 2
Design
Construction
Material
Surface

BSP nut thread
 60° outer cone
 BSP nut thread
 60° outer cone
 Connectors
 straight
 Steel
 electro galvanised

| Name | G1 (rys.) | G2 (rys.) |
|--------------|-----------|-----------|
| GAB 02 | 1/8 | 1/8 |
| GAB 02 AB 04 | 1/8 | 1/4 |
| GAB 02 AB 06 | 1/8 | 3/8 |
| GAB 02 AB 08 | 1/8 | 1/2 |
| GAB 04 | 1/4 | 1/4 |
| GAB 04 AB 06 | 1/4 | 3/8 |
| GAB 04 AB 08 | 1/4 | 1/2 |
| GAB 04 AB 10 | 1/4 | 5/8 |
| GAB 04 AB 12 | 1/4 | 3/4 |
| GAB 04 AB 16 | 1/4 | 1 |
| GAB 04 AB 20 | 1/4 | 1 1/4 |
| GAB 06 | 3/8 | 3/8 |
| GAB 06 AB 08 | 3/8 | 1/2 |
| GAB 06 AB 10 | 3/8 | 5/8 |
| GAB 06 AB 12 | 3/8 | 3/4 |
| GAB 06 AB 16 | 3/8 | 1 |
| GAB 06 AB 20 | 3/8 | 1 1/4 |
| GAB 08 | 1/2 | 1/2 |
| GAB 08 AB 12 | 1/2 | 5/8 |
| GAB 08 AB 12 | 1/2 | 3/4 |
| GAB 08 AB 16 | 1/2 | 1 |
| GAB 08 AB 20 | 1/2 | 1 1/4 |
| GAB 08 AB 24 | 1/2 | 1 1/2 |
| GAB 08 AB 32 | 1/2 | 2 |
| GAB 10 | 5/8 | 5/8 |
| GAB 10 AB 12 | 5/8 | 3/4 |
| GAB 10 AB 16 | 5/8 | 1 |
| GAB 10 AB 20 | 5/8 | 1 1/4 |

| Name | G1 (rys.) | G2 (rys.) |
|--------------|------------------|------------------|
| GAB 12 | 3/4 | 3/4 |
| GAB 12 AB 16 | 3/4 | 1 |
| GAB 12 AB 20 | 3/4 | 1 1/4 |
| GAB 12 AB 24 | 3/4 | 1 1/2 |
| GAB 12 AB 32 | 3/4 | 2 |
| GAB 16 | 1 | 1 |
| GAB 16 AB 20 | 1 | 1 1/4 |
| GAB 16 AB 24 | 1 | 1 1/2 |
| GAB 16 AB 32 | 1 | 2 |
| GAB 20 | 1 1/4 | 1 1/4 |
| GAB 20 AB 24 | 1 1/4 | 1 1/2 |
| GAB 20 AB 32 | 1 1/4 | 2 |
| GAB 24 | 1 1/2 | 1 1/2 |
| GAB 24 AB 32 | 1 1/2 | 2 |
| GAB 32 | 2 | 2 |