

## Static seals O-RING-inch



| Name            | d (rys.) | T    |
|-----------------|----------|------|
| OR1,78x1,78-70  | 1,78     | 1,78 |
| OR2,57x1,78-70  | 2,57     | 1,78 |
| OR2,9x1,78-70   | 2,90     | 1,78 |
| OR3,69x1,78-70  | 3,69     | 1,78 |
| OR4,47x1,78-70  | 4,47     | 1,78 |
| OR5,28x1,78-70  | 5,28     | 1,78 |
| OR6,07x1,78-70  | 6,07     | 1,78 |
| OR7,66x1,78-70  | 7,66     | 1,78 |
| OR9,25x1,78-70  | 9,25     | 1,78 |
| OR10,82x1,78-70 | 10,82    | 1,78 |
| OR12,42x1,78-70 | 12,42    | 1,78 |
| OR14x1,78-70    | 14       | 1,78 |
| OR15,6x1,78-70  | 15,60    | 1,78 |
| OR17,16x1,78-70 | 17,16    | 1,78 |
| OR18,77x1,78-70 | 18,77    | 1,78 |
| OR20,35x1,78-70 | 20,35    | 1,78 |
| OR21,95x1,78-70 | 21,95    | 1,78 |
| OR23,52x1,78-70 | 23,52    | 1,78 |
| OR25,12x1,78-70 | 25,12    | 1,78 |
| OR26,7x1,78-70  | 26,70    | 1,78 |
| OR28,3x1,78-70  | 28,30    | 1,78 |
| OR29,87x1,78-70 | 29,87    | 1,78 |
| OR31,47x1,78-70 | 31,47    | 1,78 |
| OR33,05x1,78-70 | 33,05    | 1,78 |
| OR34,65x1,78-70 | 34,65    | 1,78 |
| OR37,82x1,78-70 | 37,82    | 1,78 |
| OR41x1,78-70    | 41       | 1,78 |
| OR44,17x1,78-70 | 44,17    | 1,78 |

| Name             | d (rys.) | T    |
|------------------|----------|------|
| OR47,37x1,78-70  | 47,37    | 1,78 |
| OR50,52x1,78-70  | 50,52    | 1,78 |
| OR53,67x1,78-70  | 53,67    | 1,78 |
| OR56,87x1,78-70  | 56,87    | 1,78 |
| OR60,04x1,78-70  | 60,04    | 1,78 |
| OR63,22x1,78-70  | 63,22    | 1,78 |
| OR66,40x1,78-70  | 66,40    | 1,78 |
| OR69,57x1,78-70  | 69,57    | 1,78 |
| OR72,76x1,78-70  | 72,76    | 1,78 |
| OR75,94x1,78-70  | 75,94    | 1,78 |
| OR82,28x1,78-70  | 82,28    | 1,78 |
| OR88,64x1,78-70  | 88,64    | 1,78 |
| OR91,7x1,78-70   | 91,70    | 1,78 |
| OR95x1,78-70     | 95       | 1,78 |
| OR101,34x1,78-70 | 101,34   | 1,78 |
| OR107,7x1,78-70  | 107,70   | 1,78 |
| OR114x1,78-70    | 114      | 1,78 |
| OR120,4x1,78-70  | 120,40   | 1,78 |
| OR126,72x1,78-70 | 126,72   | 1,78 |
| OR133,1x1,78-70  | 133,10   | 1,78 |
| OR1,24x2,62-70   | 1,24     | 2,62 |
| OR2,06x2,62-70   | 2,06     | 2,62 |
| OR2,84x2,62-70   | 2,84     | 2,62 |
| OR3,63x2,62-70   | 3,63     | 2,62 |
| OR4,42x2,62-70   | 4,42     | 2,62 |
| OR5,23x2,62-70   | 5,23     | 2,62 |
| OR6,02x2,62-70   | 6,02     | 2,62 |
| OR7,6x2,62-70    | 7,60     | 2,62 |
| OR9,19x2,62-70   | 9,19     | 2,62 |
| OR9,13x2,62-70   | 9,13     | 2,62 |
| OR10,78x2,62-70  | 10,78    | 2,62 |
| OR12,37x2,62-70  | 12,37    | 2,62 |
| OR13,95x2,62-70  | 13,95    | 2,62 |
| OR15,54x2,62-70  | 15,54    | 2,62 |
| OR17,13x2,62-70  | 17,13    | 2,62 |
| OR18,72x2,62-70  | 18,72    | 2,62 |
| OR20,29x2,62-70  | 20,29    | 2,62 |
| OR21,9x2,62-70   | 21,90    | 2,62 |
| OR23,47x2,62-70  | 23,47    | 2,62 |
| OR25,07x2,62-70  | 25,07    | 2,62 |
| OR26,65x2,62-70  | 26,65    | 2,62 |
| OR28,25x2,62-70  | 28,25    | 2,62 |
| OR29,83x2,62-70  | 29,83    | 2,62 |
| OR33x2,62-70     | 33       | 2,62 |
| OR34,6x2,62-70   | 34,60    | 2,62 |
| OR36,17x2,62-70  | 36,17    | 2,62 |
| OR37,77x2,62-70  | 37,77    | 2,62 |

| <b>Name</b>      | <b>d (rys.)</b> | <b>T</b> |
|------------------|-----------------|----------|
| OR39,35x2,62-70  | 39,35           | 2,62     |
| OR40,95x2,62-70  | 40,95           | 2,62     |
| OR42,52x2,62-70  | 42,52           | 2,62     |
| OR44,12x2,62-70  | 44,12           | 2,62     |
| OR45,7x2,62-70   | 45,70           | 2,62     |
| OR47,3x2,62-70   | 47,30           | 2,62     |
| OR48,9x2,62-70   | 48,90           | 2,62     |
| OR50,47x2,62-70  | 50,47           | 2,62     |
| OR52,07x2,62-70  | 52,07           | 2,62     |
| OR53,65x2,62-70  | 53,65           | 2,62     |
| OR55,25x2,62-70  | 55,25           | 2,62     |
| OR56,82x2,62-70  | 56,82           | 2,62     |
| OR58,42x2,62-70  | 58,42           | 2,62     |
| OR60x2,62-70     | 60              | 2,62     |
| OR61,6x2,62-70   | 61,60           | 2,62     |
| OR63,17x2,62-70  | 63,17           | 2,62     |
| OR64,77x2,62-70  | 64,77           | 2,62     |
| OR66,35x2,62-70  | 66,35           | 2,62     |
| OR67,95x2,62-70  | 67,95           | 2,62     |
| OR69,52x2,62-70  | 69,52           | 2,62     |
| OR71,12x2,62-70  | 71,12           | 2,62     |
| OR72,7x2,62-70   | 72,70           | 2,62     |
| OR75,88x2,62-70  | 75,88           | 2,62     |
| OR82,22x2,62-70  | 82,22           | 2,62     |
| OR88,58x2,62-70  | 88,58           | 2,62     |
| OR94,93x2,62-70  | 94,93           | 2,62     |
| OR101,28x2,62-70 | 101,28          | 2,62     |
| OR107,63x2,62-70 | 107,63          | 2,62     |
| OR113,98x2,62-70 | 113,98          | 2,62     |
| OR120,33x2,62-70 | 120,33          | 2,62     |
| OR126,67x2,62-70 | 126,67          | 2,62     |
| OR133x2,62-70    | 133             | 2,62     |
| OR139,38x2,62-70 | 139,38          | 2,62     |
| OR145,73x2,62-70 | 145,73          | 2,62     |
| OR152,07x2,62-70 | 152,07          | 2,62     |
| OR158,43x2,62-70 | 158,43          | 2,62     |
| OR164,78x2,62-70 | 164,78          | 2,62     |
| OR171,13x2,62-70 | 171,13          | 2,62     |
| OR177,48x2,62-70 | 177,48          | 2,62     |
| OR183,83x2,62-70 | 183,83          | 2,62     |
| OR190,18x2,62-70 | 190,18          | 2,62     |
| OR196,53x2,62-70 | 196,53          | 2,62     |
| OR202,88x2,62-70 | 202,88          | 2,62     |
| OR209,23x2,62-70 | 209,23          | 2,62     |
| 215,57x2,62-70   | 215,57          | 2,62     |
| OR221,93x2,62-70 | 221,93          | 2,62     |
| OR228,28x2,62-70 | 228,28          | 2,62     |

| Name             | d (rys.) | T    |
|------------------|----------|------|
| OR234,63x2,62-70 | 234,63   | 2,62 |
| OR240,98x2,62-70 | 240,98   | 2,62 |
| OR247,32x2,62-70 | 247,32   | 2,62 |
| OR4,34x3,53-70   | 4,34     | 3,53 |
| OR5,94x3,53-70   | 5,94     | 3,53 |
| OR7,52x3,53-70   | 7,52     | 2,62 |
| OR9,13x3,53-70   | 9,13     | 3,53 |
| OR10,69x3,53-70  | 10,69    | 3,53 |
| OR12,29x3,53-70  | 12,29    | 3,53 |
| OR13,87x3,53-70  | 13,87    | 2,62 |
| OR15,47x3,53-70  | 15,47    | 3,53 |
| OR17,04x3,53-70  | 17,04    | 2,62 |
| OR18,64x3,53-70  | 18,64    | 3,53 |
| OR20,22x3,53-70  | 20,22    | 3,53 |
| OR21,82x3,53-70  | 21,82    | 2,62 |
| OR23,4x3,53-70   | 23,40    | 3,53 |
| OR25x3,53-70     | 25       | 3,53 |
| OR26,57x3,53-70  | 26,57    | 3,53 |
| OR28,17x3,53-70  | 28,17    | 2,62 |
| OR29,75x3,53-70  | 29,75    | 3,53 |
| OR31,34x3,53-70  | 31,34    | 3,53 |
| OR32,93x3,53-70  | 32,93    | 3,53 |
| OR34,52x3,53-70  | 34,52    | 3,53 |
| OR36,1x3,53-70   | 36,10    | 3,53 |
| OR37,7x3,53-70   | 37,70    | 3,53 |
| OR40,87x3,53-70  | 40,87    | 3,53 |
| OR44,05x3,53-70  | 44,05    | 3,53 |
| OR47,23x3,53-70  | 47,23    | 3,53 |
| OR50,4x3,53-70   | 50,40    | 3,53 |
| OR53,57x3,53-70  | 53,57    | 3,53 |
| OR56,75x3,53-70  | 56,75    | 3,53 |
| OR59,92x3,53-70  | 59,92    | 3,53 |
| OR63,1x3,53-70   | 63,10    | 3,53 |
| OR66,27x3,53-70  | 66,27    | 3,53 |
| OR69,44x3,53-70  | 69,44    | 3,53 |
| OR72,62x3,53-70  | 72,62    | 3,53 |
| OR75,8x3,53-70   | 75,80    | 3,53 |
| OR78,97x3,53-70  | 78,97    | 3,53 |
| OR85,32x3,53-70  | 85,32    | 3,53 |
| OR91,67x3,53-70  | 91,67    | 3,53 |
| OR94,84x3,53-70  | 94,84    | 3,53 |
| OR98,02x3,53-70  | 98,02    | 3,53 |
| OR101,2x3,53-70  | 101,20   | 3,53 |
| OR104,37x3,53-70 | 104,37   | 3,53 |
| OR107,54x3,53-70 | 107,54   | 3,53 |
| OR110,72x3,53-70 | 110,72   | 3,53 |
| OR113,9x3,53-70  | 113,90   | 3,53 |

| Name             | d (rys.) | T    |
|------------------|----------|------|
| OR117,07x3,53-70 | 117,07   | 3,53 |
| OR120,24x3,53-70 | 120,24   | 3,53 |
| OR123,42x3,53-70 | 123,42   | 3,53 |
| OR126,6x3,53-70  | 126,60   | 3,53 |
| OR129,77x3,53-70 | 129,77   | 3,53 |
| OR132,94x3,53-70 | 132,94   | 3,53 |
| OR136,12x3,53-70 | 136,12   | 3,53 |
| OR139,3x3,53-70  | 139,30   | 3,53 |
| OR148,82x3,53-70 | 148,82   | 3,53 |
| OR152x3,53-70    | 152      | 3,53 |
| OR158,35x3,53-70 | 158,35   | 3,53 |
| OR164,7x3,53-70  | 164,70   | 3,53 |
| OR171,05x3,53-70 | 171,05   | 3,53 |
| OR177,4x3,53-70  | 177,40   | 3,53 |
| OR183,75x3,53-70 | 183,75   | 3,53 |
| OR190,1x3,53-70  | 190,10   | 3,53 |
| OR196,45x3,53-70 | 196,45   | 3,53 |
| OR202,8x3,53-70  | 202,80   | 3,53 |
| OR209,15x3,53-70 | 209,15   | 3,53 |
| OR215,5x3,53-70  | 215,50   | 3,53 |
| OR221,85x3,53-70 | 221,85   | 3,53 |
| OR228,2x3,53-70  | 228,20   | 3,53 |
| OR234,55x3,53-70 | 234,55   | 3,53 |
| OR240,9x3,53-70  | 240,90   | 3,53 |
| OR247,25x3,53-70 | 247,25   | 3,53 |
| OR253,6x3,53-70  | 253,60   | 3,53 |
| OR266,3x3,53-70  | 266,30   | 3,53 |
| OR279x3,53-70    | 279      | 3,53 |
| OR291,7x3,53-70  | 291,70   | 3,53 |
| OR10,46x5,34-70  | 10,46    | 5,34 |
| OR12,07x5,34-70  | 12,07    | 5,34 |
| OR13,64x5,34-70  | 13,64    | 5,34 |
| OR15,24x5,34-70  | 15,24    | 5,34 |
| OR16,81x5,34-70  | 16,81    | 5,34 |
| OR18,42x5,34-70  | 18,42    | 5,34 |
| OR19,99x5,34-70  | 19,99    | 5,34 |
| OR21,59x5,34-70  | 21,59    | 5,34 |
| OR23,16x5,34-70  | 23,16    | 5,34 |
| OR24,77x5,34-70  | 24,77    | 5,34 |
| OR26,34x5,34-70  | 26,34    | 5,34 |
| OR27,94x5,34-70  | 27,94    | 5,34 |
| OR29,51x5,34-70  | 29,51    | 5,34 |
| OR31,12x5,34-70  | 31,12    | 5,34 |
| OR32,69x5,34-70  | 32,69    | 5,34 |
| OR34,29x5,34-70  | 34,29    | 5,34 |
| OR37,47x5,34-70  | 37,47    | 5,34 |
| OR40,65x5,34-70  | 40,65    | 5,34 |

| Name             | d (rys.) | T    |
|------------------|----------|------|
| OR43,82x5,34-70  | 43,82    | 5,34 |
| OR47x5,34-70     | 47       | 5,34 |
| OR50,16x5,34-70  | 50,16    | 5,34 |
| OR53,34x5,34-70  | 53,34    | 5,34 |
| OR56,52x5,34-70  | 56,52    | 5,34 |
| OR59,7x5,34-70   | 59,70    | 5,34 |
| OR62,87x5,34-70  | 62,87    | 5,34 |
| OR66,04x5,34-70  | 66,04    | 5,34 |
| OR69,22x5,34-70  | 69,22    | 5,34 |
| OR72,4x5,34-70   | 72,40    | 5,34 |
| OR75,57x5,34-70  | 75,57    | 5,34 |
| OR78,74x5,34-70  | 78,74    | 5,34 |
| OR81,92x5,34-70  | 81,92    | 5,34 |
| OR85,09x5,34-70  | 85,09    | 5,34 |
| OR88,27x5,34-70  | 88,27    | 5,34 |
| OR91,44x5,34-70  | 91,44    | 5,34 |
| OR94,62x5,34-70  | 94,62    | 5,34 |
| OR97,8x5,34-70   | 97,80    | 5,34 |
| OR100,97x5,34-70 | 100,97   | 5,34 |
| OR104,14x5,34-70 | 104,14   | 5,34 |
| OR107,32x5,34-70 | 107,32   | 5,34 |
| OR110,5x5,34-70  | 110,50   | 5,34 |
| OR113,67x5,34-70 | 113,67   | 5,34 |
| OR116,84x5,34-70 | 116,84   | 5,34 |
| OR120,02x5,34-70 | 120,02   | 5,34 |
| OE123,19x5,34-70 | 123,19   | 5,34 |
| OR126,37x5,34-70 | 126,37   | 5,34 |
| OR129,54x5,34-70 | 129,54   | 5,34 |
| OR132,72x5,34-70 | 132,72   | 5,34 |
| OR135,89x5,34-70 | 135,89   | 5,34 |
| OR139,07x5,34-70 | 139,07   | 5,34 |
| OR142,24x5,34-70 | 142,24   | 5,34 |
| OR148,59x5,34-70 | 148,59   | 5,34 |
| OR151,77x5,34-70 | 151,77   | 5,34 |
| OR158,12x5,34-70 | 158,12   | 5,34 |
| OR164,47x5,34-70 | 164,47   | 5,34 |
| OR170,82x5,34-70 | 170,82   | 5,34 |
| OR177,17x5,34-70 | 177,17   | 5,34 |
| OR183,52x5,34-70 | 183,52   | 5,34 |
| OR189,87x5,34-70 | 189,87   | 5,34 |
| OR196,22x5,34-70 | 196,22   | 5,34 |
| OR202,57x5,34-70 | 202,57   | 5,34 |
| OR208,92x5,34-70 | 208,92   | 5,34 |
| OR215,27x5,34-70 | 215,27   | 5,34 |
| OR221,62x5,34-70 | 221,62   | 5,34 |
| OR227,97x5,34-70 | 227,97   | 5,34 |
| OR234,32x5,34-70 | 234,32   | 5,34 |

| <b>Name</b>      | <b>d (rys.)</b> | <b>T</b> |
|------------------|-----------------|----------|
| OR240,67x5,34-70 | 240,67          | 5,34     |
| OR247,02x5,34-70 | 247,02          | 5,34     |
| OR253,37x5,34-70 | 253,37          | 5,34     |